



Associated British Ports South Wales

NOTICE TO MARINERS

NO 23 OF 2015

NOTIFICATION OF SOUTH CARDIFF CARDINAL BUOY BEING RESTORED TO NORMAL SERVICE

Mariners are advised that with immediate effect the following buoy is reported as being restored to Normal Service: -

C-1 – South Cardiff Cardinal Buoy: -

Latitude 51° 24.15” N

Longitude 03° 08.48” W

HARBOUR MASTER, SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

14th May 2015

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk