



Associated British Ports South Wales

NOTICE TO MARINERS

NO 14 OF 2015

NOTIFICATION OF SOUTH CARDIFF CARDINAL BUOY BEING REPORTED AS BEING BACK ON STATION BUT WITH TOP MARK MISSING

Mariners are advised that with immediate effect the following buoy is reported as being back on Station but with the Top Mark Missing: -

C-1 – South Cardiff Cardinal Buoy: -

Latitude 51° 24.15" N

Longitude 03° 08.48" W

HARBOUR MASTER, SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

7th April 2015

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk