



# Associated British Ports South Wales

## NOTICE TO MARINERS

NO 10 OF 2016

### NOTIFICATION OF WEST USK LIGHTED BUOY MISSING ITS TOP MARK

Mariners are advised that with immediate effect the following buoy is reported as having its Top Mark Missing: -

**West Usk Lighted Buoy: -**

**Latitude 51° 31.673" N  
Longitude 002° 58.502" W**

**HARBOUR MASTER, SOUTH WALES  
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY**

15<sup>th</sup> April 2016

All ABP South Wales Notices to Mariners may be viewed on: - [www.southwalesports.co.uk](http://www.southwalesports.co.uk)

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.