

NO 48 OF 2016

NOTIFICATION OF

<u>LEADING LIGHT ON LIBERTY STEEL BERTH BEING REPORTED AS</u> 'UPPER LIGHT EXTINGUISHED'

Mariners are advised that the Julians Pill leading lights on Liberty Steel, in the River Usk, are not operating as prescribed, upper light is extinguished.

Position:

Latitude 51°33.32' N Longitude 002°57.90' W

HARBOUR MASTER, SOUTH WALES

Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

20th December 2016

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.