

Associated British Ports South Wales

NOTICE TO MARINERS.

NO 58 of 2025

Number Two Buoy Out of Position, Newport Approach

Mariners are advised that Number Two buoy, Port Hand Lateral Mark, Newport Approach Channel. Is reported as being approximately 50m south of charted position.

Work to investigate and reposition Number Two Buoy back to its charted position will take place W/C **1st of December**.

HARBOUR MASTER SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

Date 28/11/2025

South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.